

5. Torque bolts to 44 Nm. (32 ft-bl, 4.5kgf-m)

Note: Install Yoshimura Chassis Protector one side at a time. Removing both left and right side engine mount bolts simultaneously can cause engine to drop or shift and as a result the holes may be misaligned.