

STREET SERIES

Qualified Manufacturer Declared "Replacement Part"

| APPLICATION | 1025 |
|--|--|
| YEAR | MODEL |
| 2011~2016 | Suzuki GSX-R600 / 750 |
| PRODUCT | |
| 160020220 | R77 Stainless Steel Slip-On Exhaust System with Carbon Fiber Sleeve; Carbon Fiber Endcap |
| 160020520 | R77 Stainless Steel Slip-On Exhaust System with Stainless Steel Sleeve; Carbon Fiber Endcap |
| 160020550 | R77 Stainless Steel Slip-On Exhaust System with Stainless Steel Sleeve; Stainless Steel Endcap |
| 9 | lifornia, it is illegal to modify the emission control system, which includes the fuel injection of any vehicle. ow to remove and replace your stock exhaust in order to install this product otherwise have it installed by a professional |
| mechanic. Keep a depending on the | all stock parts from your existing system as some components may be necessary to install your new Yoshimura exhaust application. |
| | instructions before beginning installation. Exhaust system can be extremely hot. Let motorcycle cool down before beginning ys wear hand and eye protection and take precautionary measures to avoid injury. |
| Stock Muffler | |
| Stainless Steel Clamp Stock Nut Insulator Heat | Stock Bolt and Washer |
| | 3 |
| | $ \begin{array}{c} 1 \\ -4 \\ -4 \\ -6 \end{array} $ S = Stoc |

| No. | Part # | Description | Qty |
|-----|--|---|-----|
| 1 | 11600-435 | Yoshimura Tailpipe | 1 |
| 2 | CRR77F126W SRR77F126W SRR77126W-SS | Yoshimura Muffler CF Sleeve; CF Endcap SS Sleeve; CF Endcap SS Sleeve; SS Endcap | 1 |
| 3 | 1121-MPCA 1121-MPCAX | Muffler Clamp CF Sleeve SS Sleeve | 1 |
| 4 | HT SHLDR77 | Muffler Clamp Heatshield | 1 |
| 5 | 27-61M | Exhaust Clamp | 1 |

| 6 | RACE-82MM | 82mm Springs | 2 |
|----|----------------------|---|---|
| 7 | 11600-HS | Yoshimura Heatshield | 1 |
| 8 | M6X10BHS | 6mm x 10mm Button Head Screw | 1 |
| 9 | M6X1U | 6mm x 1.0 U-Nut | 1 |
| 10 | M6X12BHS | 6mm x 12mm Button Head Screw | 1 |
| ** | INS-03-K INS-04-K | Low Vol. Insert SS Endcap CF Endcap | 1 |
| ** | ST-200 | Spring Puller Tool | 1 |
| ** | 17029 | Yoshimura Sticker Sheet | 1 |

5420 Daniels Street Chino, CA 91710 Tel (800) 634-9166 Fax (909) 591-2198 <u>www.yoshimura-rd.com</u> 1160020(220,520,550)_5.doc

-TOOLS REQUIRED-

Metric Socket Set Combination Wrench Set Torque Wrench Metric Allen Wrench Set

-REMOVAL-

- 1. Remove stock heatshield by removing the heatshield screw.
- 2. Remove the stock rubber grommet on the heatshield bracket.
- 3. Loosen exhaust clamp.
- 4. While supporting the muffler securely, remove the muffler mount bolt.
- 5. Slide the stock muffler assembly off midpipe.

-INSTALLATION-

- 1. Small parts installation.
 - a) Install U-Nut provided in the kit on the lower hole of the stock heatshield bracket where the stock rubber grommet was removed.
 - b) Install rubber heatshield on muffler clamp. See diagram for reference. (Note: Some trimming of the heatshield may be required.)
 - c) Slide muffler clamp over Yoshimura muffler.
- 2. Installing the Yoshimura muffler assembly.
 - a) Slide provided exhaust clamp over Yoshimura tailpipe.
 - b) Slide Yoshimura Slip-On System onto stock midpipe.
 - c) Align muffler mount and bolt using stock bolts. (Note: If necessary, remove springs on tailpipe to muffler to twist and align properly.)
 - d) Tighten and torque exhaust clamp to 21 ft-lb. (29Nm, 2.9kgf-m)
 - e) Tighten and torque muffler mount to 33 ft-lb. (45Nm, 4.5kgf-m)
 - f) Install Yoshimura heatshield using the (2) provided 6mm x 10mm screws.
- 3. Fitment check and Notes.
 - a) Before starting motorcycle, check for proper clearance between new exhaust system and rear suspension (i.e. tire, swing-arm, brake, rear shock, engine, and etc.) If any problem is found, please carefully follow through the installation steps again. If problem still persists, please call Yoshimura Tech Department at (800) 634-9166 / in CA (909) 628-4722.
 - b) It is recommended that the muffler and tailpipe be wiped down with rubbing alcohol to remove oil and fingerprints. This will help prevent tarnishing of the finish after the exhaust is heated up.
 - c) NOTE: After starting motorcycle, it is normal for new exhaust system and muffler to emit smoke until oil residue burns off.